

Código	Eni	gm	Ford	ZF	Mercedes	VW	BMW	CITROËN	NISSAN	HYUNDAI	HONDA	TOYOTA	volvo	Outras
1299	Eni Rotra ATF (1)	DEXRON IID	ESP-M2C166-H, ESP-M2C138-CJ	236.2										
1297	Eni Rotra ATF II D	DEXRON IID	MERCON	236.6	TE-ML 05L, 09, 17C; (*): TE-ML 04D, 11A, 14A									Allison C-4; Caterpillar TO-2; Voith H55.6335.xx; MAN 339 type V1(*), 339 type Z1
1267	Eni Rotra ATF II E (2)	DEXRON IIIH, DEXRON IIE		236.9	TE-ML 14C, 16L, 16R (*): TE-ML 03D, 04D, 14B, 17C, 20B, 25B;									MAN 339 type V2, Z2, Z11; Voith H55.6336.xx
14650e	Autol ATF III D (2)	DEXRON IIIG (GM 6417-M)	MERCON (no MERCON V), M2C 138-CJ, M2C 166-H									Type T-III (Aisin Warner)		Voith H55.6335xx (G 607); Allison C-4; Bosch TE-ML 09; Caterpillar TO-2
1298	Eni Rotra ATF III	DEXRON IIIH	MERCON											(Allison TES-389), (Allison C-4)
1310	Eni Rotra ATF MULTI	DEXRON IIIH	MERCON, MERCON V	236.9(*)	(*): TE-ML 04D, 14B, 20B, 25B	G 052 025 (09M), G 052 990 (09A)	LT 71141		MATIC D, J, K	SP-II/ III	ATF Z-1	T-IV	97340, 97341	(Allison TES-295); Chrysler ATF+3/+4; MAN 339 type V1/ Z2/ Z11; JASO 1-A; AISIN JWS 3309; Voith H55.6335 (G607); Mazda ATF M-III
0909e	Eni Rotra ATF MBX (3)	DEXRON ULV, VI, II, IID, IIE, IIIG, IIIH, Suffix A	MERCON ULV/LV/V/SP, WSS-M2C 922-A1, WSS-M2C 949-A	236.10, 236.12, 236.14, 236.15, 236.17, 236.41, 236.5, 236.6	TE-ML 11A, 11B; Lifeguard 6 + 8	G 052 025, 055, 162, 533, 990; G 055 005, 025, 540; G 060 162	7045E, 8072B, LA2634, LT71141; ATF3/ 3+/ 6; M-1375.4	B71 2340	D, J, K, S, W	SP-II/ -III/ -IV/ -IV RR; RED-1K; NWS-9638	DW-1/ 3.0 / 3.1/ ATF-Z1 (except in CVT)	DII; T/ T-III/ T-IV; WS	1161540	AISIN WARNER JWS 3324, JWS 3309, AAW-1, AAW-2; Allison C-4; Chrysler ATF+/ +2/ +3/ +4; JASO M315 Type 1A LV; Mazda FZ, M-III, Type T-IV; Mitsubishi SP-II/ III/ J2/ J3/ PA; Isuzu ATF II, III; Jaguar JLM 20238/ 20292/ 21044; Subaru ATF HP; Suzuki ATF 3314/ 3317
4109	Eni Rotra DCT (1, 2)		WSS-M2C 936-A/ M2C 218-A1/ M2C 200-D2	236.21, 236.22, 236.24, 236.25, 239.21		G 052 182, 529, 536; G 055 529, 536	DCTF-1, DCTF-1+, DCTF-2, LT-5	9734 S2		Hyundai/Kia			1161838, 1161839, D1, D2	Mitsubishi Dia-Queen SSTF-1; Porsche/ZF FFL-3; Ferrari TF DCT-F3; Borg Warner; Bugatti Veyron; Renault EDC/ R7D/ DC4/ DW5/ DW6; Fiat 9.55550-HE2/ MZ6; Chrysler Powershift 6-speed, 68044345 EA & GA
4119	Eni Rotra CVT (1, 2)	DEX-CVT	WSS-M2C 928-A	236.20		G-052-180, G-052-516	Mini Cooper EZL799/ 799A		NS-1, NS-2, NS- 3	CVT-J1/ SP III (CVT model)	HMMF (sin embrague de arranque) / HCF2	CVTF TC/ FE		Chrysler/Dodge/Jeep NS-2/Mopar CVTF+4; Mazda JWS 3320; Daihatsu Amix CVTF DC/ DFCE/ DFE; Mitsubishi SP-III (only in CVT), CVTF-J1/ J4 /J4+; Subaru ECVT, iCVT, iCVT FG/ NS-2, Lineartronic High Torque (HT) CVTF, Lineartronic chain CVTF/ CVTF II; Suzuki CVTF TC, 3320, NS-2, Green 1, Green 2, Green 1V

(1) importado Itália
(2) importado Alemanha
(3) importado Benelux

(*) aprovado
() "adequado para uso"

